

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER Governor

GALE F. McKEACHNIE Lieutenant Governor

Representatives Present During the Inspection				
OGM	Joe Helfrich Reclamation Specialist III			
Company	Dan Guy			

# **Inspection Report**

Permit Number:	C0070016		
Inspection Type:	PARTIAL		
Inspection Date:	Wednesday, November 19, 2003		
Start Date/Time:	11/19/2003 1:00:00 PM		
End Date/Time:	11/19/2003 3:00:00 PM		
Last Inspection:	Wednesday, October 01, 2003		

Inspector: Joe Helfrich, Reclamation Specialist III

Weather: sunny 45

Accepted by: dhaddock 11/25/2003

Permitee: MOUNTAIN COAL CO
Operator: MOUNTAIN COAL CO

Site: GORDON CREEK 2, 7 & 8 MINES
Address: HC 35 BOX 380, HELPER UT 84526

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages		Mineral Ownership	Types of Operations		
180.00	Total Permitted	✓ Federal	Underground		
34.88	Total Disturbed	☐ State	Surface		
	Phase I	☐ County	Loadout		
	Phase II	<b>✓</b> Fee	Processing		
	Phase III	☐ Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

The purpose of this visit was to conduct a partial inspection of the reclaimed site.

Inspector's Signature:	Date	Tuesday, November 25, 2003

Joe Helfrich, Reclamation Specialist III

Inspector ID Number: 1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining



Permit Number: C0070016 Inspection Type: PARTIAL

Inspection Date: Wednesday, November 19, 2003

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	<b>✓</b>		<b>✓</b>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<b>✓</b>		<b>✓</b>	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations	<b>✓</b>		<b>✓</b>	
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.	b Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070016 Inspection Type: PARTIAL

Inspection Date: Wednesday, November 19, 2003

Page 3 of 3

## 2. Signs and Markers

Signs containing the required information were posted at the site.

## 4.b Hydrologic Balance: Sediment Ponds and Impoundments

The three cells of the sediment pond were dry at the time of this inspection. There was approximately 2" of snow covering the reclaimed area.

#### 4.e Hydrologic Balance: Effluent Limitations

Hard copies of the DMR's for September and October showed no discharge.